

ANIMAL RESOURCE CENTER



PROGRESS UPDATE 12/28/2020



**CAT/SMALL ANIMAL ROOMS – LEFT SIDE
(FROM MAIN VIEWING AREA)**



**CAT/SMALL ANIMAL ROOMS – RIGHT SIDE
(FROM MAIN VIEWING AREA)**



**CAT/SMALL ANIMAL ROOMS LT/RT & ADOPTABLE DOGS AHEAD
(FROM MAIN VIEWING AREA)**



**ADOPTABLE DOGS AREA – RIGHT HALF
(FROM MAIN VIEWING AREA)**



**ADOPTABLE DOGS AREA – LEFT HALF
(FROM MAIN VIEWING AREA)**



**ADOPTABLE DOGS AREA ENTRY & CORRIDOR TO DOG KENNELS
(FROM MAIN VIEWING AREA)**



**ADOPTABLE DOGS AREA ENTRY & CORRIDOR TO DOG KENNELS
(FROM ENTRY DOOR FRAME)**



**ADOPTABLE DOGS AREA – RIGHT SIDE LOOKING TO THE LEFT
(FROM INSIDE THE AREA)**



**ADOPTABLE DOGS AREA – LEFT SIDE LOOKING TO THE RIGHT
(FROM INSIDE THE AREA)**



**INSIDE CORRIDOR OF NEW
VET OFFICE WING**



SURGICAL PREP ROOM LEADING TO SURGERY ROOM



STORAGE ROOM LEADING TO LAUNDRY ROOM



FOOD PREP ROOM



EXAM ROOM



VET TECH / VET OFFICE ROOM



VET TECH/EXAM/STORAGE/FOOD PREP CORRIDOR



EXISTING CORRIDOR LEADING TO NEW VET WING



NEWLY INSTALLED HVAC UNITS



**WEST SIDE OF DOG BOARDING ADDITION
(EXTERIOR CONCRETE DOG RUN RECENTLY INSTALLED)**



**EAST SIDE OF DOG BOARDING ADDITION
(EXTERIOR CONCRETE DOG RUN RECENTLY INSTALLED)**